

Mr Duncan MacArthur EDSL 13-14 Cofferidge Close Stony Stratford Milton Keynes MK11 1BY Dorothy Grobler
Energy Performance of Building Division
2nd Floor SW, Fry Building,
2 Marsham Street,
London
SW1P 4DF

Direct Line: 0303 444 6532 Fax: 0303 444 3313

E-mail: dorothy.grobler@communities.gov.uk

Web Site: www.communities.gov.uk

13 January 2020

Dear Mr MacArthur,

Thank you for your submission of 29 November 2019, on behalf of on behalf of EDSL requesting approval for the Bug-Fix re-validation of the DSM interface software, TAS v9.5.

I am pleased to be able to advise you that the report produced by AECOM confirms that EDSL TAS v9.5 is compliant with the approved national calculation methodology (SBEM version 5.6.a) and has been approved. This letter of approval supersedes any previous letter issued by MHCLG in relation to this software.

The approval is based on the following:

- The scope of the validation at the current time has focused on compliance of the generated certificates and reports using the business and operational logic, both published and agreed, at the Commercial Energy Performance Certificate Conventions Group meetings.
- The approval has taken account of the information provided by you and testing by AECOM, as set out in their report of 13 January 2020. The department is, therefore, satisfied that the software correctly replicates satisfactory agreement with the certificate and report templates. A copy of AECOM report recommending approval is attached for ease of reference.
- The software is approved as fit for commercial use in its current state and form
  including the Checksum results set out at Annex A. These Checksum results set out
  in Annex A replace those included in previous approval letters. Any later variant or
  version will need to be submitted separately for approval.
- It is the responsibility of software providers to ensure that the software they produce provides accurate calculations in line with the National Calculation Methodology (NCM) for which it is approved.
- This approval does not imply any liability is accepted by the department for software calculation inaccuracies.

Please note that a formal publication of the approval will be made in due course.

Yours sincerely,

**Dorothy Grobler** 

Appoint

## **Checksum results**

Below are the results from the checksum carried out on SBEM interface software version 5.6 which must be present in this current version.

File Name	Checksum Value
TBD.exe	D8267EE8B94B30D571B5E330347C9462
TPD.exe	018B790F95A583AF2855BA4D24B8E1F8
UKBRStudio2013.exe	61E5D82B21B904800A4EDD211F5160D0